






Installation: Isolite® 2




1 Locate available HVE and remove cap.




2 Attach hose connector to power vacuum hose and connect to HVE.




3 Plug power supply into outlet and connect power to hose.



4 Connect the Control Head to the Power Hose and then re-insert the Light Stick. Be careful not to twist Control Head.



5 Attach Vacuum Light Pipe to Control Head.



To order additional mouthpieces, isolation systems or parts/accessories, please visit www.zyris.com or call us at 855.749.5880.